

Laughlin Boat Accidents

Lake Mohave – Near Katherine’s Landing Sunken Vessel Following Vessel Fire



Colorado River

1 PWC Collided with 3 Other PWCs

Subject Fled – Hit and Run – Leading to Arrest



Lake Mohave

Grounded Vessel Leading to Submersion



Colorado River
PWC Collides with Dock and Docked London Jet Boat
(Commercial Vessel)
Common Issue



Colorado River

Single PWC into Wall on Side of River Near Hotels – Injury
Right Photo – Engine Separated from Drivetrain due to Collision
Forces



Colorado River
Sunken Vessel – Near Drowning
Collision with Drinking Water Authority Intake Buoy/Anchor Chain



Colorado River Vessel Fire



PWC Collision with Pontoon Boat Multiple Major Trauma Injuries – Hospitalized Colorado River



Near Fatal – Colorado River
Left Photo – Impacting Vessel
Right Photo – Impacted Vessel

Minimal Damage due to Ramping/Jumping Effect Caused by PWCs
2 Females to Hospital Including Juvenile Flown to Vegas Due to Trauma



Fatal – Colorado River

Photos from Reconstruction Efforts

Left Photo: Impacting Vessel - Center Bottom Photo: Impacted Vessel
Right Photo – Perceived View of Operator Immediately Prior to Impact
Minimal Damage due to Ramping/Jumping Effect Caused by PWCs



Fatal Collision – Colorado River
Female Operator was Intoxicated with Alcohol and Drugs
Collided with Dock and Docked Vessel at Speed – Leading to Ejection, Death,
and Sunken Vessel

